

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD

Name of Facility Address City County
 EAST COLUMBUS BOYS & GIRLS CLUB POOL 1429 MORRIS RD COLUMBUS
 Operator Address City County
 1429 MORRIS RD COLUMBUS

Deficiencies found on the inspection are marked with an (X). A check mark (✓) indicates satisfactory compliance. Each blank under column (24-26) should be filled in with above symbols as appropriate.

	Item No.	24-59	Notes	
POOL WATER	Type supply: Public			
	Water supply approved, adequate	1	✓	
	Depth properly marked	2	✓	
	Overflow facilities adequate	3	✓	
	Constant water level	4	✓	
	Turnover adequate	5	✓	
	Disinfectant residual concentration	6	✓ (see addendum)	
	pH (7.2-7.8)	7	✓ (see addendum)	
	Total Alkalinity	8	✓ (see addendum)	
	Calcium Hardness	9	✓	
	Cyanuric Acid	10	✓	
PUMPING FILTRATION AND TREATMENT SYSTEM	Clarity	11	✓	
	Pump operating properly	12	✓	
	Filters functioning properly	13	✓	
	Hair & lint strainers functioning properly	14	✓	
	Skimmers/Gutters maintained & operating properly	15	✓	
	Chemical feeders operating properly	16	✓	
	Recirculation and filtration equipment readily accessible	17	✓	
	DECK AND POOL AREA	Pool & Decks clean and in good repair	18	✓
		Night lighting adequate	19	✓ (see addendum)
		Hot & cold water under pressure	20	✓
	WATER AND FACILITIES	Adequate toilet facilities & showers	21	✓
SEWAGE DISPOSAL		Sewage disposal method: Public	22	✓
	Life line in place/Separation of wading pool	23	✓	
	Warning/Safety sign posted in clearview of pool area	24	✓	
	SAFETY PRECAUTIONS	First aid kits available & properly equipped	25	✓
		Emergency & lifesaving equipment in conspicuous place	26	✓
		Emergency phone provided and hard wired	27	✓
		Gas cylinder precautions adequate	28	✓
		Proper barrier around pool	29	✓
		Main drains properly covered and maintained	30	✓
		Certified Pool Operator	31	✓ (see addendum)
		Lifeguard(s) (if provided) has proper certification	32	✓
OPERATOR AND RECORDS		Trained operator on duty	33	✓
		Appropriate records on file	34	✓
		Pool test kit(s) available and adequate for all necessary tests	35	✓
	Other	36	✓	

Gauge Readings:

Influent Pressure 0.00 psi
 Effluent Pressure 0.00 psi
 Flow Rate Main Pool 300.00 gpm
 Flow Rate Wading Pool 0.00 gpm

Laboratory Results:

Alkalinity 80.00 ppm
 Coliform Count 0.00
 Plate Count 0.00

Name of Bactericide In Use: tri chl Rate 0.00 ppm
 Name of Stabilizer In Use: _____ Rate 0.00 ppm
 Name of Filter System In Use: _____
 Algae Control Measures: _____

Remarks

pool looks fine close pool if chemical level are not correct and keep closed until corrected.

✓ SATISFACTORY
UNSATISFACTORY

ENFORCEMENT
 None
 Permit Suspended
 Closed Voluntarily
 Re-inspection needed within days
 Hearing Requested/Recommended

Permit No.
 106-P10

Expiration Date
 2011 12 31
 YR MO DA

Purpose
 1. Routine
 2. Re-inspection
 3. Request
 4. Complaint
 5. Other
 1

Length of Inspection 00:45 Hours

Pool Type:
 Swimming/Pool
 Spa
 Special Purpose Pool:
 Activity/Interactive/Wading
 Type: Pool

Required Turnover Rate: 285.00 gpm
 Type of Disinfection: _____
 Required Concentration: _____
 6 0
 Bather Load

Purpose
 1. None
 2. Water
 3. Other
 1

Reason for Sample: _____

Date of Inspection Discussed with (Signature) Inspected by (Signature)

07/11/2011

life guard
 Title:

Kathy McCarley
 Title: Environmental Health Technician

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD ADDENDUM

Name of Facility	Address	City	County
EAST COLUMBUS BOYS & GIRLS CLUB POOL	1429 MORRIS RD	COLUMBUS	
Operator	Address	City	County
	1429 MORRIS RD	COLUMBUS	

Item Number	Notes
6	3.0
7	7.4
8	80
19	pool closes at 5 pm
31	crystal pools