

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD

Name of Facility: TILLIS POOL - COLUMBUS PARKS & RECREATION
 Address: 1417 13TH AVE
 City: COLUMBUS
 County: _____
 Operator: _____
 Address: 100 10TH ST
 City: COLUMBUS
 County: _____

Deficiencies found on the inspection are marked with an (X). A check mark (✓) indicates satisfactory compliance. Each blank under column (24-26) should be filled in with above symbols as appropriate.

	Item No.	24-59	Notes
POOL WATER	Type supply: Public	1	✓
	Water supply approved, adequate	2	X (see addendum)
	Depth properly marked	3	✓
	Overflow facilities adequate	4	✓
	Constant water level	5	✓ (see addendum)
	Turnover adequate	6	✓ (see addendum)
	Disinfectant residual concentration	7	✓ (see addendum)
	pH (7.2-7.8)	8	✓ (see addendum)
	Total Alkalinity	9	✓
	Calcium Hardness	10	✓
	Cyanuric Acid	11	✓
PUMPING AND FILTRATION AND TREATMENT SYSTEM	Pump operating properly	12	✓
	Filters functioning properly	13	✓
	Hair & lint strainers functioning properly	14	✓
	Skimmers/Gutters maintained & operating properly	15	✓
	Chemical feeders operating properly	16	✓
	Recirculation and filtration equipment readily accessible	17	✓
	DECK AND POOL AREA	Pool & Decks clean and in good repair	18
Night lighting adequate		19	✓
Hot & cold water under pressure		20	✓
Adequate toilet facilities & showers		21	✓
WATER AND FACILITIES	Sewage disposal method: Public	22	✓
		Life line in place/Separation of wading pool	23
	Warning/Safety sign posted in clearview of pool area	24	✓
	First aid kits available & properly equipped	25	✓
	Emergency & lifesaving equipment in conspicuous place	26	✓
	Emergency phone provided and hard wired	27	✓ (see addendum)
	Gas cylinder precautions adequate	28	✓
	Proper barrier around pool	29	✓
	Main drains properly covered and maintained	30	✓
	Certified Pool Operator	31	✓
	SAFETY PRECAUTIONS	Lifeguard(s) (if provided) has proper certification	32
Trained operator on duty		33	✓
Appropriate records on file		34	✓
Pool test kit(s) available and adequate for all necessary tests		35	✓
Other		36	✓

Gauge Readings:

Influent Pressure: 0.00 psi
 Effluent Pressure: 0.00 psi
 Flow Rate Main Pool: 0.00 gpm
 Flow Rate Wading Pool: 0.00 gpm

Laboratory Results:

Alkalinity: 0.00 ppm
 Coliform Count: 0.00
 Plate Count: 0.00

Name of Bactericide In Use: cal hypo
 Name of Stabilizer In Use:
 Name of Filter System In Use:
 Algae Control Measures:

Rate: 0.00 ppm
 Rate: 0.00 ppm

Remarks

Date of Inspection

Discussed with (Signature)

Inspected by (Signature)

07/26/2011

Jake
 Title: cpo

Kathy McCarley
 Title: Environmental Health Technician

SATISFACTORY
 UNSATISFACTORY

ENFORCEMENT
 None
 Permit Suspended
 Closed Voluntarily
 Re-inspection needed within days
 Hearing Requested/Recommended

Permit No.
 106-P15

Expiration Date
 2010 12 30
 YR MO DA

Purpose
 3
 1. Routine
 2. Re-inspection
 3. Request
 4. Complaint
 5. Other

Length of Inspection: 00:30 Hours

Pool Type:
 Swimming/Pool
 Spa
 Special Purpose Pool:
 Activity/Interactive/Wading
 Type: Pool

Required Turnover Rate: 130.00gpm
 Type of Disinfection:
 Required Concentration:

4 0
 Bather Load

Purpose

 1. None
 2. Water
 3. Other

Reason for Sample:

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD ADDENDUM

Name of Facility	Address	City	County
TILLIS POOL - COLUMBUS PARKS & RECREATION	1417 13TH AVE	COLUMBUS	
Operator	Address	City	County
	100 10TH ST	COLUMBUS	

Item Number	Notes
2	add no diving markers where needed
5	165
6	2.0
7	7.2
8	60
27	add address to phone