

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD

Name of Facility: RIGDON PARK POOL
 Address: 1835 RIVERLAND DR
 City: COLUMBUS
 County: _____

Operator: _____
 Address: 100 10TH ST
 City: COLUMBUS
 County: _____

Deficiencies found on the inspection are marked with an (X). A check mark (✓) indicates satisfactory compliance. Each blank under column (24-26) should be filled in with above symbols as appropriate.

	Item No.	24-59	Notes	
POOL WATER	Type supply: Public			
	Water supply approved, adequate	1	✓	
	Depth properly marked	2	✓	
	Overflow facilities adequate	3	✓	
	Constant water level	4	✓	
	Turnover adequate	5	✓	
	Disinfectant residual concentration	6	✓	
	pH (7.2-7.8)	7	✓ (see addendum)	
	Total Alkalinity	8	✓ (see addendum)	
	Calcium Hardness	9	✓ (see addendum)	
	Cyanuric Acid	10	✓	
PUMPING FILTRATION AND TREATMENT SYSTEM	Clarity	11	✓	
	Pump operating properly	12	✓	
	Filters functioning properly	13	✓	
	Hair & lint strainers functioning properly	14	✓	
	Skimmers/Gutters maintained & operating properly	15	✓	
	Chemical feeders operating properly	16	✓	
	Recirculation and filtration equipment readily accessible	17	✓	
	DECK AND POOL AREA	Pool & Decks clean and in good repair	18	✓
		Night lighting adequate	19	✓
		Hot & cold water under pressure	20	✓
	WATER AND FACILITIES	Adequate toilet facilities & showers	21	✓
SEWAGE DISPOSAL		Sewage disposal method: Public	22	✓
	SAFETY PRECAUTIONS	Life line in place/Separation of wading pool	23	✓
Warning/Safety sign posted in clearview of pool area		24	✓	
First aid kits available & properly equipped		25	✓	
Emergency & lifesaving equipment in conspicuous place		26	✓	
Emergency phone provided and hard wired		27	✓	
Gas cylinder precautions adequate		28	✓	
Proper barrier around pool		29	✓	
Main drains properly covered and maintained		30	✓	
OPERATOR AND RECORDS		Certified Pool Operator	31	✓
		Lifeguard(s) (if provided) has proper certification	32	✓
		Trained operator on duty	33	✓
	Appropriate records on file	34	✓	
	Pool test kit(s) available and adequate for all necessary tests	35	✓	
	Other	36	✓	

Gauge Readings:

Influent Pressure: 0.00 psi
 Effluent Pressure: 0.00 psi
 Flow Rate Main Pool: 1500.00 gpm
 Flow Rate Wading Pool: 0.00 gpm

Laboratory Results:

Alkalinity: 80.00 ppm
 Coliform Count: 0.00
 Plate Count: 0.00

Name of Bactericide In Use: lq chl
 Name of Stabilizer In Use:
 Name of Filter System In Use:
 Algae Control Measures:

Rate: 0.00 ppm
 Rate: 0.00 ppm

Remarks

pool deck has some cracks fix asap

Date of Inspection: 06/29/2011

Discussed with (Signature):

Inspected by (Signature):

unable to read
 Title:

Kathy McCarley
 Title: Environmental Health Technician

✓ SATISFACTORY
 UNSATISFACTORY

ENFORCEMENT
 ✓ None
 Permit Suspended
 Closed Voluntarily
 Re-inspection needed within days
 Hearing Requested/Recommended

Permit No.
 106-P18

Expiration Date
 2011 12 31
 YR MO DA

Purpose
 1. Routine
 2. Re-inspection
 3. Request
 4. Complaint
 5. Other
 1

Length of Inspection: 00:45 Hours

Pool Type:
 Swimming/Pool
 Spa
 Special Purpose Pool:
 Activity/Interactive/Wading
 Type: Pool

Required Turnover Rate: 540.00gpm
 Type of Disinfection:
 Required Concentration:
 3 0 0
 Bather Load

Purpose
 1. None
 2. Water
 3. Other
 1

Reason for Sample:

MUSCOGEE COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SECTION
PUBLIC SWIMMING POOL INSPECTION RECORD ADDENDUM

Name of Facility
RIGDON PARK POOL
Operator

Address
1835 RIVERLAND DR
Address
100 10TH ST

City
COLUMBUS
City
COLUMBUS

County
County

Item Number	Notes
6	2.5
7	7.6
8	80