

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD

Name of Facility: SHIRLEY B WINSTON POOL
 Address: 5025 STEAM MILL RD
 City: COLUMBUS
 County: []
 Operator: []
 Address: 100 10TH ST
 City: COLUMBUS
 County: []

Deficiencies found on the inspection are marked with an (X). A check mark (✓) indicates satisfactory compliance. Each blank under column (24-26) should be filled in with above symbols as appropriate.

	Item No.	24-59	Notes	
POOL WATER	Type supply: Public			
	Water supply approved, adequate	1	✓	
	Depth properly marked	2	✓	
	Overflow facilities adequate	3	✓	
	Constant water level	4	✓	
	Turnover adequate	5	✓	
	Disinfectant residual concentration	6	✓ (see addendum)	
	pH (7.2-7.8)	7	✓ (see addendum)	
	Total Alkalinity	8	✓ (see addendum)	
	Calcium Hardness	9	✓	
	Cyanuric Acid	10	✓	
PUMPING AND TREATMENT SYSTEM	Clarity	11	✓	
	Pump operating properly	12	✓	
	Filters functioning properly	13	✓	
	Hair & lint strainers functioning properly	14	✓	
	Skimmers/Gutters maintained & operating properly	15	✓	
	Chemical feeders operating properly	16	✓	
	Recirculation and filtration equipment readily accessible	17	✓	
	DECK AND POOL AREA	Pool & Decks clean and in good repair	18	✓
		Night lighting adequate	19	✓
		Hot & cold water under pressure	20	✓
		Adequate toilet facilities & showers	21	✓
SEWAGE DISPOSAL	Sewage disposal method: Public	22	✓	
	Life line in place/Separation of wading pool	23	✓	
SAFETY PRECAUTIONS	Warning/Safety sign posted in clearview of pool area	24	✓	
	First aid kits available & properly equipped	25	✓	
	Emergency & lifesaving equipment in conspicuous place	26	✓	
	Emergency phone provided and hard wired	27	✓	
	Gas cylinder precautions adequate	28	✓	
	Proper barrier around pool	29	✓	
	Main drains properly covered and maintained	30	✓	
	Certified Pool Operator	31	✓	
	Lifeguard(s) (if provided) has proper certification	32	✓	
	Trained operator on duty	33	✓	
OPERATOR AND RECORDS	Appropriate records on file	34	✓	
	Pool test kit(s) available and adequate for all necessary tests	35	✓	
	Other	36	✓	

Gauge Readings:

Influent Pressure: 12.00 psi
 Effluent Pressure: 9.00 psi
 Flow Rate Main Pool: 1100.00 gpm
 Flow Rate Wading Pool: 0.00 gpm

Laboratory Results:

Alkalinity: 60.00 ppm
 Collform Count: 0.00
 Plate Count: 0.00

Name of Bactericide In Use: lq chl
 Name of Stabilizer In Use:
 Name of Filter System In Use:
 Algae Control Measures:

Rate: 0.00 ppm
 Rate: 0.00 ppm

Remarks

Date of Inspection: 07/21/2011

Discussed with (Signature):

Inspected by (Signature):

unable to read
 Title: manager

Kathy McCarley
 Title: Environmental Health Technician

✓ SATISFACTORY
 UNSATISFACTORY

ENFORCEMENT
 ✓ None
 Permit Suspended
 Closed Voluntarily
 Re-inspection needed within days
 Hearing Requested/Recommended

Permit No.
 106-P23

Expiration Date
 2011 12 31
 YR MO DA

Purpose
 1. Routine
 2. Re-inspection
 3. Request
 4. Complaint
 5. Other
 1

Length of Inspection: 00:45 Hours

Pool Type:
 ✓ Swimming/Pool
 Spa
 Special Purpose Pool:
 Activity/Interactive/Wading
 Type: Pool

Required Turnover Rate: 540.00gpm
 Type of Disinfection:
 Required Concentration:

Bather Load: 3 0 0

Purpose
 1. None
 2. Water
 3. Other

Reason for Sample:

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD ADDENDUM

Name of Facility	Address	City	County
SHIRLEY B WINSTON POOL	5025 STEAM MILL RD	COLUMBUS	
Operator	Address	City	County
	100 10TH ST	COLUMBUS	

Item Number	Notes
6	2.0
7	7.2
8	60