

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD

Name of Facility	Address	City	County
COURTYARD BY MARRIOTT SPA	3501 COURTYARD WAY	COLUMBUS	Muscogee
Operator	Address	City	County
Chris Smith	ONE MARRIOTT DR	WASHINGTON	

Deficiencies found on the inspection are marked with an (X). A check mark (✓) indicates satisfactory compliance. Each blank under column (24-28) should be filled in with above symbols as appropriate.

	Item No.	24-59	Notes
			Type supply: Public
POOL WATER	Water supply approved, adequate	1	✓
	Depth properly marked	2	✓
	Overflow facilities adequate	3	✓
	Constant water level	4	✓
	Turnover adequate	5	✓ (see addendum)
	Disinfectant residual concentration	6	✓ (see addendum)
	pH (7.2-7.8)	7	✓ (see addendum)
	Total Alkalinity	8	✓ (see addendum)
	Calcium Hardness	9	✓ (see addendum)
	Cyanuric Acid	10	✓ (see addendum)
	Clarity	11	✓
PUMPING FILTRATION AND TREATMENT SYSTEM	Pump operating properly	12	✓
	Filters functioning properly	13	✓
	Hair & lint strainers functioning properly	14	✓
	Skimmers/Gutters maintained & operating properly	15	✓
	Chemical feeders operating properly	16	✓
	Recirculation and filtration equipment readily accessible	17	✓
	Pool & Decks clean and in good repair	18	✓
	Night lighting adequate	19	✓ (see addendum)
	Hot & cold water under pressure	20	✓ (see addendum)
	Adequate toilet facilities & showers	21	✓ (see addendum)
DECK AND POOL AREA WATER AND FACILITIES	Sewage disposal method: Public	22	✓
	Life line in place/Separation of wading pool	23	✓ (see addendum)
	Warning/Safety sign posted in clearview of pool area	24	✓
	First aid kits available & properly equipped	25	✓
	Emergency & lifesaving equipment in conspicuous place	26	✓
	Emergency phone provided and hard wired	27	✓
	Gas cylinder precautions adequate	28	✓ (see addendum)
	Proper barrier around pool	29	✓
	Main drains properly covered and maintained	30	✓
	Certified Pool Operator	31	✓ (see addendum)
SAFETY PRECAUTIONS	Lifeguard(s) (if provided) has proper certification	32	✓ (see addendum)
	Trained operator on duty	33	✓
	Appropriate records on file	34	✓
	Pool test kit(s) available and adequate for all necessary tests	35	✓
	Other	36	✓ (see addendum)
OPERATOR AND RECORDS			

Gauge Readings:

Influent Pressure	0	psi
Effluent Pressure	0	psi
Flow Rate Main Pool	0	gpm
Flow Rate Wading Pool	0	gpm

Laboratory Results:

Alkalinity	0	ppm
Coliform Count	0	
Plate Count	0	

Name of Bactericide in Use: Cal Hypo
 Name of Stabilizer in Use:
 Name of Filter System in Use:
 Algae Control Measures:

Rate 0 ppm
 Rate 0 ppm

Remarks

✓ **SATISFACTORY**
 UNSATISFACTORY

ENFORCEMENT

✓ None
 Permit Suspended
 Closed Voluntarily
 Re-inspection needed within days
 Hearing Requested/Recommended

Permit No.

106-P29

Expiration Date

2013	12	31
YR	MO	DA

Purpose

1. Routine
2. Re-inspection
3. Request
4. Complaint
5. Other

1

Length of Inspection 0.45 Hours

Pool Type:

Swimming/Pool
 ✓ Spa
 Special Purpose Pool:
 Activity/Interactive/Wading
 Type: Pool

Required Turnover Rate: 33 gpm

Type of Disinfection: Cal Hypo

Required Concentration:

			8
Bather Load			

Purpose

1. None
2. Water
3. Other

1

Reason for Sample:

Date of Inspection

12/06/2011

Discussed with (Signature)

Chris Smith

Chris Smith
 Title: CPO

Inspected by (Signature)

Ashley Basset

Ashley Basset
 Title: Environmental Health Specialist I

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD ADDENDUM

Name of Facility
 COURTYARD BY MARRIOTT SPA

Address
 3501 COURTYARD WAY

City
 COLUMBUS

County
 Muscogee

Operator

Address
 ONE MARRIOTT DR

City
 WASHINGTON

County

Chris Smith

Item Number	Notes
5	100 GPM
6	3.0
7	7.2
8	100
9	NA
10	NA
19	6 AM-11 PM
20	in adjacent hotel rooms
21	in adjacent hotel rooms and lobby
23	NA-3ft and less
28	NA
31	Chris Smith
32	NA
36	water fountain, clock

Ashley Barnett