

MUSCOGEE COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SECTION
PUBLIC SWIMMING POOL INSPECTION RECORD

Name of Facility: Doubletree Hotel Columbus Pool
Address: 5351 SIDNEY SIMONS BLVD
City: COLUMBUS
County: _____
Operator: _____
Address: 600 BROOKSTONE CENTRE PKWY
City: COLUMBUS
County: _____

Deficiencies found on the inspection are marked with an (X). A check mark (✓) indicates satisfactory compliance. Each blank under column (24-26) should be filled in with above symbols as appropriate.

	Item No.	24-59	Notes	
POOL WATER	Type supply: Public			
	Water supply approved, adequate	1	✓	
	Depth properly marked	2	✓	
	Overflow facilities adequate	3	✓	
	Constant water level	4	✓	
	Turnover adequate	5	✓ (see addendum)	
	Disinfectant residual concentration	6	✓ (see addendum)	
	pH (7.2-7.8)	7	✓ (see addendum)	
	Total Alkalinity	8	✓ (see addendum)	
	Calcium Hardness	9	✓	
	Cyanuric Acid	10	✓	
PUMPING FILTRATION AND TREATMENT SYSTEM	Clarity	11	✓	
	Pump operating properly	12	✓	
	Filters functioning properly	13	✓	
	Hair & lint strainers functioning properly	14	✓	
	Skimmers/Gutters maintained & operating properly	15	✓	
	Chemical feeders operating properly	16	✓	
	Recirculation and filtration equipment readily accessible	17	✓	
	Pool & Decks clean and in good repair	18	X (see addendum)	
	Night lighting adequate	19	✓	
	Hot & cold water under pressure	20	✓	
	DECK AND POOL AREA WATER AND FACILITIES SEWAGE DISPOSAL	Adequate toilet facilities & showers	21	✓
Sewage disposal method: Public		22	✓	
Life line in place/Separation of wading pool		23	✓	
Warning/Safety sign posted in clearview of pool area		24	✓	
First aid kits available & properly equipped		25	✓	
SAFETY PRE-CAUTIONS		Emergency & lifesaving equipment in conspicuous place	26	✓
		Emergency phone provided and hard wired	27	✓
		Gas cylinder precautions adequate	28	✓
		Proper barrier around pool	29	✓
		Main drains properly covered and maintained	30	✓
		Certified Pool Operator	31	✓
	Lifeguard(s) (if provided) has proper certification	32	✓	
	OPERATOR AND RECORDS	Trained operator on duty	33	✓
		Appropriate records on file	34	✓
		Pool test kit(s) available and adequate for all necessary tests	35	✓
		Other	36	✓

Gauge Readings:
Influent Pressure: 0.00 psi
Effluent Pressure: 0.00 psi
Flow Rate Main Pool: 0.00 gpm
Flow Rate Wading Pool: 0.00 gpm

Laboratory Results:
Alkalinity: 0.00 ppm
Coliform Count: 0.00
Plate Count: 0.00

Name of Bactericide In Use: tri chl Rate: 0.00 ppm
Name of Stabilizer In Use: Rate: 0.00 ppm
Name of Filter System In Use:
Algae Control Measures:

✓ SATISFACTO
UNSATISFAC

ENFORCEMENT
None
Permit Suspended
Closed Voluntarily
Re-inspection needed within days
Hearing Requested/Recommended

Permit No. 106-P80

Expiration Date
2013 12 31
YR MO D.

Purpose: 1. Routine, 2. Re-inspe, 3. Request, 4. Complair, 5. Other
I

Length of Inspection: 00:45 Hours

Pool Type: Swimming/Pool, Spa
Special Purpose Pool: Activity/Interactive/
Type: Pool

Required Turnover Rate: 49.0
Type of Disinfection:
Required Concentration:

Bather Load: 3 5

Purpose: 1. None, 2. Water, 3. Other

Reason for Sample:

Remarks

Date of inspection: 11/30/2011
Discussed with (Signature): alvin johnson, Title: gm
Inspected by (Signature): Kathy McCarley, Title: Environmental Health Technician

MUSCOGEE COUNTY HEALTH DEPARTMENT
 ENVIRONMENTAL HEALTH SECTION
 PUBLIC SWIMMING POOL INSPECTION RECORD ADDENDUM

Name of Facility	Address	City	County
Doubletree Hotel Columbus Pool	5351 SIDNEY SIMONS BLVD	COLUMBUS	
Operator	Address	City	County
	600 BROOKSTONE CENTRE PKWY	COLUMBUS	

Item Number	Notes
5	60
6	3.5
7	7.2
8	70
18	fix ladder in pool asap