

MUSCOGEE COUNTY HEALTH DEPARTMENT  
 ENVIRONMENTAL HEALTH SECTION  
 PUBLIC SWIMMING POOL INSPECTION RECORD

Name of Facility: Doubletree Hotel Columbus Spa  
 Address: 5351 Sidney Simons BLVD UNIT  
 City: COLUMBUS County:   
 Operator: 600 Brookstone PKWY  
 Address: City: COLUMBUS County:

Deficiencies found on the inspection are marked with an (X). A check mark (✓) indicates satisfactory compliance. Each blank under column (24-26) should be filled in with above symbols as appropriate.

	Item No.	24-59	Notes
POOL WATER	Type supply: Public		
	Water supply approved, adequate	1	✓
	Depth properly marked	2	✓
	Overflow facilities adequate	3	✓
	Constant water level	4	✓
	Turnover adequate	5	✓
	Disinfectant residual concentration	6	✓ (see addendum)
	pH (7.2-7.8)	7	✓ (see addendum)
	Total Alkalinity	8	✓ (see addendum)
	Calcium Hardness	9	✓
	Cyanuric Acid	10	✓
PUMPING AND TREATMENT SYSTEM	Clarity	11	✓
	Pump operating properly	12	✓
	Filters functioning properly	13	✓
	Hair & lint strainers functioning properly	14	✓
	Skimmers/Gutters maintained & operating properly	15	✓
	Chemical feeders operating properly	16	✓
	Recirculation and filtration equipment readily accessible	17	✓
DECK AND POOL AREA FACILITIES	Pool & Decks clean and in good repair	18	✓
	Night lighting adequate	19	✓
	Hot & cold water under pressure	20	✓
	Adequate toilet facilities & showers	21	✓
SEWAGE DISPOSAL	Sewage disposal method: Public	22	✓
	Life line in place/Separation of wading pool	23	✓
	Warning/Safety sign posted in clearview of pool area	24	X (see addendum)
SAFETY PRECAUTIONS	First aid kits available & properly equipped	25	✓
	Emergency & lifesaving equipment in conspicuous place	26	✓
	Emergency phone provided and hard wired	27	✓
	Gas cylinder precautions adequate	28	✓
	Proper barrier around pool	29	✓
	Main drains properly covered and maintained	30	✓
	Certified Pool Operator	31	✓
OPERATOR AND RECORDS	Lifeguard(s) (if provided) has proper certification	32	✓
	Trained operator on duty	33	✓
	Appropriate records on file	34	✓
	Pool test kit(s) available and adequate for all necessary tests	35	✓
	Other	36	✓

Gauge Readings:

Influent Pressure: 0.00 psi  
 Effluent Pressure: 0.00 psi  
 Flow Rate Main Pool: 0.00 gpm  
 Flow Rate Wading Pool: 0.00 gpm

Laboratory Results:

Alkalinity: 0.00 ppm  
 Coliform Count: 0.00  
 Plate Count: 0.00

Name of Bactericide In Use: tri chl  
 Name of Stabilizer In Use:  
 Name of Filter System In Use:  
 Algae Control Measures:

Rate: 0.00 ppm  
 Rate: 0.00 ppm

Remarks

Date of Inspection: 11/30/2011  
 Discussed with (Signature): alvin johnson  
 Inspected by (Signature): Kathy McCarley

Title: gm

Title: Environmental Health Technician

✓ SATISFACTO  
 UNSATISFAC

ENFORCEMENT

- ✓ None
- Permit Suspended
- Closed Voluntarily
- Re-inspection needed within days
- Hearing Requested/Recommended

Permit No.

106-P81

Expiration Date

2011 12 31  
 YR MO D.

Purpose

- 1. Routine
- 2. Re-inspe
- 3. Request
- 4. Complair
- 5. Other

Length of Inspection: 00:30 Hours

Pool Type:

- Swimming/Pool
- ✓ Spa
- Special Purpose Pool: Activity/Interactive<sup>a</sup>
- Type: Pool

Required Turnover Rate: 60.0  
 Type of Disinfection:  
 Required Concentration:

Bather Load: 0

Purpose

- 1. None
- 2. Water
- 3. Other

Reason for Sample:

MUSCOGEE COUNTY HEALTH DEPARTMENT  
 ENVIRONMENTAL HEALTH SECTION  
 PUBLIC SWIMMING POOL INSPECTION RECORD ADDENDUM

<b>Name of Facility</b>	<b>Address</b>	<b>City</b>	<b>County</b>
Doubletree Hotel Columbus Spa	5351 Sidney Simons BLVD UNIT	COLUMBUS	
<b>Operator</b>	<b>Address</b>	<b>City</b>	<b>County</b>
	600 Brookstone PKWY	COLUMBUS	

Item Number	Notes
6	3.0
7	7.2
8	60
24	need new sign