

MUSCOGEE COUNTY HEALTH DEPARTMENT  
ENVIRONMENTAL HEALTH SECTION  
PUBLIC SWIMMING POOL INSPECTION RECORD

Name of Facility **Address** **City** **County**  
YMCA (Thayer) Spa 1327 1st AVE COLUMBUS  
Operator **Address** **City** **County**  
4384 Warm Springs RD COLUMBUS

Deficiencies found on the inspection are marked with an (X). A check mark (✓) indicates satisfactory compliance. Each blank under column (24-26) should be filled in with above symbols as appropriate.

	Item No.	24-59	Notes	
<b>POOL WATER</b>	Type supply: Public			
	Water supply approved, adequate	1	✓	
	Depth properly marked	2	✓	
	Overflow facilities adequate	3	✓	
	Constant water level	4	✓	
	Turnover adequate	5	✓	
	Disinfectant residual concentration	6	✓ (see addendum)	
	pH (7.2-7.8)	7	✓ (see addendum)	
	Total Alkalinity	8	✓ (see addendum)	
	Calcium Hardness	9	✓	
	Cyanuric Acid	10	✓	
<b>PUMPING FILTRATION AND TREATMENT SYSTEM</b>	Clarity	11	✓	
	Pump operating properly	12	✓	
	Filters functioning properly	13	✓	
	Hair & lint strainers functioning properly	14	✓	
	Skimmers/Gutters maintained & operating properly	15	✓	
	Chemical feeders operating properly	16	✓	
	Recirculation and filtration equipment readily accessible	17	✓	
	<b>DECK AND POOL AREA</b>	Pool & Decks clean and in good repair	18	✓
		Night lighting adequate	19	✓
		Hot & cold water under pressure	20	✓
	<b>WATER AND FACILITIES</b>	Adequate toilet facilities & showers	21	✓
<b>SEWAGE DISPOSAL</b>		Sewage disposal method: Public	22	✓
	Life line in place/Separation of wading pool	23	✓	
	Warning/Safety sign posted in clearview of pool area	24	✓	
	First aid kits available & properly equipped	25	✓	
	<b>SAFETY PRE-CAUTIONS</b>	Emergency & lifesaving equipment in conspicuous place	26	✓
		Emergency phone provided and hard wired	27	✓
	Gas cylinder precautions adequate	28	✓	
	Proper barrier around pool	29	✓	
	Main drains properly covered and maintained	30	✓	
	Certified Pool Operator	31	✓	
	Lifeguard(s) (if provided) has proper certification	32	✓	
<b>OPERATOR AND RECORDS</b>	Trained operator on duty	33	✓	
	Appropriate records on file	34	✓	
Pool test kit(s) available and adequate for all necessary tests	35	✓		
Other	36	✓		

Gauge Readings:

Influent Pressure 0.00 psi  
Effluent Pressure 0.00 psi  
Flow Rate Main Pool 35.00 gpm  
Flow Rate Wading Pool 0.00 gpm

Laboratory Results:

Alkalinity 0.00 ppm  
Coliform Count 0.00  
Plate Count 0.00

Name of Bactericide In Use: lc  
Name of Stabilizer In Use:  
Name of Filter System In Use:  
Algae Control Measures:

Rate 0.00 ppm  
Rate 0.00 ppm

Remarks  
spa is 525 gallons

Date of Inspection Discussed with (Signature)

11/29/2011

kim pilcher  
Title: cpo

Inspected by (Signature)

Kathy McCarley  
Title: Environmental Health Technician

✓ SATISFACTO  
UNSATISFAC

ENFORCEMENT

- ✓ None
- Permit Suspended
- Closed Voluntarily
- Re-inspection needed within days
- Hearing Requested/Recommended

Permit No.

106-P85

Expiration Date

2011 12 31  
YR MO D.

Purpose

1. Routine
2. Re-inspe.
3. Request
4. Complair
5. Other

Length of Inspection 00:30 Hours

Pool Type:

- Swimming/Pool
- ✓ Spa
- Special Purpose Pool: Activity/Interactive/ Type: Pool

Required Turnover Rate: 35.0

Type of Disinfection: \_\_\_\_\_

Required Concentration: \_\_\_\_\_

3  
Bather Load

Purpose

1. None
2. Water
3. Other

Reason for Sample:

MUSCOGEE COUNTY HEALTH DEPARTMENT  
 ENVIRONMENTAL HEALTH SECTION  
 PUBLIC SWIMMING POOL INSPECTION RECORD ADDENDUM

<b>Name of Facility</b>	<b>Address</b>	<b>City</b>	<b>County</b>
YMCA (Thayer) Spa	1327 1st AVE	COLUMBUS	
<b>Operator</b>	<b>Address</b>	<b>City</b>	<b>County</b>
	4384 Warm Springs RD	COLUMBUS	

Item Number	Notes
6	3.0
7	7.4
8	60